



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.:	DK/ULD/QAR11.0003/11	Page 1 of 1
QAR Free Ref. No.:	4792136000	Status: Issued
Details of change:	Reassessment audit and addition of protection "t".	Date of issue: 2026-04-29
Location(s) audited:	Inor Process AB Travbanegatan 10 213 77 Malmö Sweden	Valid until: 2029-05-06 Audit date: 2026-03-26
Issuing ExCB:	ULD - UL Solutions (Demko)	
Manufacturer:	Inor Process AB Travbanegatan 10 213 77 Malmö	
Location of Manufacturer:	Sweden	
Product information:	Electronic units and converters; signal conditioners; temperature sensors and transmitters for use in explosive atmospheres	
Type of protection:	Flameproof "d" Increased Safety "e" Intrinsic Safety "i" Encapsulation "m" Dust Ignition Protection by Enclosure "t"	
Related QARs:	DK/ULD/QAR11.0003/00 DK/ULD/QAR11.0003/03 DK/ULD/QAR11.0003/06 DK/ULD/QAR11.0003/09 DK/ULD/QAR11.0003/01 DK/ULD/QAR11.0003/04 DK/ULD/QAR11.0003/07 DK/ULD/QAR11.0003/10 DK/ULD/QAR11.0003/02 DK/ULD/QAR11.0003/05 DK/ULD/QAR11.0003/08	
Related Certificates (manual insertion)::		
Related Certificates (automatic linking)::		
Related Certificates for previous versions:	IECEX KIWA 14.0001X issue: 0 IECEX KIWA 14.0002X issue: 1 IECEX KIWA 14.0011X issue: 0 IECEX KIWA 15.0015X issue: 1 IECEX KIWA 16.0005X issue: 0 IECEX KIWA 16.0006X issue: 1 IECEX KIWA 16.0016X issue: 2 IECEX KIWA 16.0017X issue: 1 IECEX KIWA 16.0018X issue: 0 IECEX KIWA 16.0018X issue: 3 IECEX KIWA 16.0019X issue: 2 IECEX KIWA 17.0027X issue: 1 IECEX KIWA 17.0028X issue: 1 IECEX KIWA 17.0029X issue: 1 IECEX KIWA 17.0030X issue: 1 IECEX PTB 14.0006X issue: 0 IECEX KIWA 14.0001X issue: 1 IECEX KIWA 14.0010X issue: 0 IECEX KIWA 14.0011X issue: 1 IECEX KIWA 15.0016X issue: 0 IECEX KIWA 16.0005X issue: 1 IECEX KIWA 16.0016X issue: 0 IECEX KIWA 16.0016X issue: 3 IECEX KIWA 16.0017X issue: 2 IECEX KIWA 16.0018X issue: 1 IECEX KIWA 16.0019X issue: 0 IECEX KIWA 16.0019X issue: 3 IECEX KIWA 17.0027X issue: 2 IECEX KIWA 17.0028X issue: 2 IECEX KIWA 17.0029X issue: 2 IECEX KIWA 17.0030X issue: 2 IECEX PTB 14.0007X issue: 0 IECEX KIWA 14.0002X issue: 0 IECEX KIWA 14.0010X issue: 1 IECEX KIWA 15.0015X issue: 0 IECEX KIWA 15.0016X issue: 1 IECEX KIWA 16.0006X issue: 0 IECEX KIWA 16.0016X issue: 1 IECEX KIWA 16.0017X issue: 0 IECEX KIWA 16.0017X issue: 3 IECEX KIWA 16.0018X issue: 2 IECEX KIWA 16.0019X issue: 1 IECEX KIWA 17.0027X issue: 0 IECEX KIWA 17.0028X issue: 0 IECEX KIWA 17.0029X issue: 0 IECEX KIWA 17.0030X issue: 0 IECEX PRE 17.0061X issue: 0	

Comments: The scope of this assessment for Dust Ignition Protection by Enclosure "t" is for a Local Assembler per IECEx OD 203. Please contact ExCB for additional information.